



### Site Inspection and Hazard Report

Supervisor Ben Trager

Site Address 36 Davies Crescent  
Gooseberry Hill

Job Number 25027

Site Hazards	Yes	No	Comments (Take Photos of all items noted)
Overhead powerlines	✓		
Asbestos fencing / contaminated ground. (if discovered warning signs to be installed and photographs to be saved)		✓	
Retaining walls (possible fall zones)		✓	
Trip hazards		✓	
Existing excavations, holes or embankments		✓	
Bores	✓		Windmill above cut
Septic systems and leach drains			
Dangerous native fauna (e.g. snakes, bees, spiders etc)	✓		
Site access / restrictions for evacuation		✓	
Steep gradients		✓	
Fences, gates	✓		Site fenced due to school.
Fence removal required		✓	
Trafficable curbs / foot path	✓		
Water meter & power supply	✓		
Traffic management required		✓	
Water supply (tanks - check flow)		✓	
Existing swimming pools (secured and boarded up)		✓	
Large sand and rubbish piles		✓	
Nearby schools/public venue access	✓		
Other			

Kerb and Footpath Condition	Yes	No	Comments
Existing curb damage	✓		
Existing footpath damage		NA	
Boundary fences	✓		
Existing damage	—		old fences to boundary on Nth.

Power	Yes	No	Comments
If overhead power onsite:		✓	Overhead Power across road
Note voltage of powerlines & estimate ground clearance			

